
HANDLING WITH CRANES OR HOISTS


The hooks, spreader bars or other devices used for lifting, should have rounded edges and/or protective covers. Capro recommends the use of safety hooks with an integrated latch to prevent the hook from accidentally slipping off the loop. Hooks should have a sufficiently large radius to prevent squeezing the loop.

When the FIBC is suspended, the loops must be vertical, without any twists or knots.



RIGHTING FIBCS

To right an FIBC that has toppled on its side, an endless fabric sling, wound through all the lifting loops, should be used. Any attempt to lift the FIBC using fewer loops than those provided, may result in the loops being torn off.



EMPTYING FIBCS

FIBCs are usually emptied by gravity, but can also be emptied by suction. When emptied by gravity through a bottom discharge spout, the rate of discharge can be controlled by restricting the outlet. Flow can be stopped by lowering the FIBC onto the discharge load. FIBCs with the plain/solid bottom can be emptied by cutting the base of the bag. Again, the flow can be stopped by lowering the bag onto the discharged load. No one should stand under an FIBC during discharge.

A bottom discharge spout should be opened only when the FIBC is suspended over a safety support that will prevent injury to the operator in the event of a failure of the lifting device.

Under no circumstances should anyone stand underneath a suspended FIBC; or their arm beneath an unsupported FIBC.

FILLING FIBCS

FIBCs are preferably filled with the base of the bag supported by the ground or a pallet, and the body of the bag supported by the top lift device. If the FIBC has a discharge spout, it should be tied off or closed before filling.

STABILITY OF FILLED FIBCS

When filled the ratio of the height of the bag to the width/ diameter of the bag should not be more than 2:1. Stability of bags may be improved by vibration during or after filling.

LIFTING FIBCS.

When lifting FIBCs with a fork lift truck, be sure that the fork lift tines are spaced correctly. All lifting loops, sleeves, or other lifting devices should be vertical, so that no damaging lateral forces will be created. Be sure that the lifting loops are not twisted.




HORIZONTAL CARRYING WITH FORK LIFTS TRUCKS

The fork lift truck must be suitable for the load to be carried. When traveling with a FIBC hanging from the fork lift tines, there is a danger of the truck becoming unstable. The FIBC should be held close to the mast and as low as possible with the mast tilted slightly backwards. Make sure that the FIBC body will be damaged by the wheels of the truck the load should not restrict the view of the driver.

FIBC must not be dragged. The truck should be brought to a stop before the FIBC is raised or lowered.



CORRECT WRONG WRONG




STACKING OF FILLED FIBCS

When stacking filled FIBCs 2 or more high, every effort should be made to ensure that the stack is stable. Where possible, the stack should be formed against at least two retaining walls, preferably 3, to achieve maximum stability. Generally, the higher the stack, the greater number of retaining walls required.

Where only free stacking is possible, a pyramid method should be used

FIBCs should not be pushed into a stack as this can cause damage to the sides or back of

the FIBC



STORAGE OF FILLED FIBCS

If FIBCs are stored outside, attention should be paid to the top closure. Be sure the top closure is properly tied off. FIBCs should be covered with waterproof, U.V protected material to avoid water collecting on the top of the FIBC and to prevent damage from sunlight.

Be sure that FIBCs are not standing in water.

HAZARDOUS MATERIALS

Special care should be taken when handling bags with UN or DOT regulated materials. For questions concerning the material, refer to the suppliers MSDS. Questions concerning FIBCs should be referred to your Capro contact.

EXPLOSIVE MATERIALS AND AREAS

If FIBCs are to be filled or emptied in flammable or explosive atmospheres, special features such as anti-stat material should be utilized.

DO

DO observe the handling instructions on the label

DO check that the discharge spout is closed off before filling

DO ensure that the filled FIBC is stable

DO close the top inlet correctly

DO inflate the liner prior to filling

DO take appropriate measures in regard to dust control

DO use lifting gear of sufficient capacity to take the suspended load

DO ensure that the edges of the fork lift tines are smooth, or protected

DO adjust the fork lift tines to the correct width for the FIBC being handled

DO keep the fork lift tines on the fork lift level

DO ensure that crane hooks are of adequate size and well rounded

DO consider the possibility and effects of static electricity

DO protect the FIBCs from rain and prolonged sunlight

DO ensure that FIBCs are adequately secured in transportation

DO dispose of FIBCs in accordance with ecological requirements

DON'T

DON'T exceed the Safe Working Load under any circumstance

DON'T fill FIBCs unevenly

DON'T stop or start suddenly during transportation

DON'T subject FIBCs to sudden lifts or stops

DON'T allow personnel under suspended FIBC

DON'T allow FIBC to project over the side of a vehicle or pallet

DON'T tilt the mast of the fork lift

forward

DON'T withdraw fork lift tines prior to relieveing all the load on the lifting device

DON'T stack FIBCs unless sure of stability